


Having Problems Obtaining an Image with the Braun Multiscan 4000 & CyberView-X Software

Try this:

Open the CyberView-X application & from the 'Scan' option select 'Preferences'



Select the 'ICE/ROC/GEM' tab - & ensure ALL are enabled...

